



Field Repair Order

Print Date: 18-Jul-12

Service Record ID: 152143

Instrument Location: Shaw Environmental
919 Kerr Research Drive

Contact: Steve Markham

Ada

OK 74820

Serial Number: MD2307

Leave Home: 8:30

Repair Date: 3/15/2011

Arrive Customer: 14:00

Technician: 464

Leave Customer: 15:00

Process Date: 201103

Arrive NC: 19:00

Problem Description:

This is a pm request. No reported problems at this time. 5-10 day gold service response MZ245

Solution Description:

Performed inspection and p.m. Cleaned and check all instrument components all good. Checked turntable sensor and adjusted. Performed calibration temperature and pressure, measure microwave power all good, checked microwave leakage and no leaks. Performed standard test no problems occur. Completed all instrument checks and did not find any other problems.

152143	990000	SERVICE LABOR, FIEL	1	\$865.00
Total Price:				\$865.00

Signed by:

Signature Date:

CEM Verification: _____ Date: _____

CEM Corporation
3100 Smith Farm Road
Matthews, NC 28106-0200

Web: www.cem.com/service
E-mail: service@cem.com
Fax: 704.821.4368
Tel: 704.821.9204